## Oil Field Environmental Incident Summary

Incident: 20161020235249 Date/Time of Notice: 10/20/2016 23:52
Responsible Party: ENERPLUS RESOURCES USA CORPORATION
Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: BAIT 149-95-36C-25H

Field Name: EAGLE NEST Well File #: 31071

Date Incident:10/19/2016Time Incident:20:00Facility ID Number:County:MCKENZIETwp:149Rng:95Sec:36Qtr:

Location Description: Well site

Submitted By: Tony Lucero Received By:

Contact Person: Chuck Antle

US BANK TOWER 950 17TH ST STE 2200 DENVER, CO 80202

General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:3 MileDistance Nearest Water Well:3 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 2 Barrels 2 Barrels 2 barrels

Brine Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 10/21/2016 Clean Up Concluded: 10/20/2016

Risk Evaluation:

No applicable health hazards.

Areal Extent:

Entire release was contained within secondary containment dike.

## Potential Environmental Impacts:

Entire release was contained within secondary containment dike.

## Action Taken or Planned:

Ensure proper tank filling procedures are followed.

Wastes Disposal Location: All recovered waste that cannot be salvaged will be shipped offsite to an approved disposal facility.

Agencies Involved:

## **Updates**

Date: 10/21/2016 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release, due to a tank overflow, was contained within diking according to the report. NDIC retains oversight.